



---

## NIC port e1a through e1b in slot 1 are non-functional

[https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/NIC\\_port\\_e1a\\_through\\_e1b\\_in\\_slot\\_1are...](https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/NIC_port_e1a_through_e1b_in_slot_1are...)

Updated: Wed, 22 Apr 2026 02:10:09 GMT

### Applies to

FAS 8300

### Issue

No link lights on the NIC in slot 1 after testing with known good cables and with different switch ports.