



X4010WBORA1T9NTE running NA51 firmware having high latency

https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/X4010WBORA1T9NTE_running_NA51_fir...

Updated: Wed, 22 Apr 2026 02:13:57 GMT

Applies to

- ONTAP 9
- X4010WBORA1T9NTE

Issue

Drives exhibiting high IO / read and write latency, no evident EMS drive errors.