



Understanding the Impact of Brocade Defect (FOS-817953) on ONTAP Upgrade

https://kb-stage.netapp.com/on-prem/Switches/Broadcom-KBs/Understanding_the_Impact_of_Brocade...

Updated: Wed, 22 Apr 2026 02:10:28 GMT

Applies to

- ONTAP 9.15.1 and later
- Brocade FC Switches
- 8.2.1 through 8.2.1d
- 8.2.2 through 8.2.2b

Issue

- Third-party devices sending GZS or GAZS commands may cause the zoning database on the switch to become truncated on version 8.2.1 through 8.2.1d & 8.2.2 through 8.2.2b (Brocade FOS-817953)
- If this occurs, the relevant zone entry within the switch's configuration file may get corrupted.