



## FAS2620/FAS2650/AFF A200 HA rebooting: System input power lost due Outdated internal switch of SP

[https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/FAS2620\\_FAS2650\\_AFF\\_A200\\_HA\\_rebo...](https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/FAS2620_FAS2650_AFF_A200_HA_rebo...)

Updated: Wed, 24 Jun 2026 07:13:54 GMT

### Applies to

- ONTAP 9
- AFF A200
- FAS2620
- FAS2650

### Issue

- Both nodes reboot frequently at the same time
- SP logs show 'system input power lost'

Record 760: Sun Aug 23 23:12:33 2020 [SP.emergency]: System input power lost

```
Record 793: Mon Aug 24 11:22:50 2020 [SP.emergency]: System input power lost
Record 828: Wed Aug 26 06:42:30 2020 [SP.emergency]: System input power lost
Record 869: Sun Sep 13 15:57:22 2020 [SP.emergency]: System input power lost
Record 933: Wed Sep 16 09:04:24 2020 [SP.emergency]: System input power lost
```