



IFGRP missing after NIC replacement

https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/IFGRP_missing_after_NIC_replacement

Updated: Wed, 22 Apr 2026 02:10:22 GMT

Applies to

- ONTAP 9

Issue

- Fault on NIC caused it to disappear in ONTAP.
- Swapped NIC with another similar NIC in another slot on the same node.
- Removing NIC while ONTAP running to simulate NIC failure.