



Onboard port missing after ontap upgrade

https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Onboard_port_missing_after_ontap_upgr...

Updated: Wed, 22 Apr 2026 02:10:14 GMT

Applies to

- AFF-A300
- Ontap

Issue

- Onboard port missing after ONTAP update
- In the below example e0m is missing
- Expected output from `net port show`

Port	IPspace	Broadcast	Domain	Link	MTU	Speed (Mbps) Admin/Oper	Health Status
------	---------	-----------	--------	------	-----	----------------------------	------------------

```

-----
a0a      Default      a0a      up    9000      -/-      healthy
e0M      Default      Default  up    1500      auto/1000 healthy
e0a      Cluster      Cluster  up    9000      auto/10000 healthy
e0b      Cluster      Cluster  up    9000      auto/10000 healthy

```

- Unexpected output from `net port show`

```

Port      IPspace      Broadcast Domain Link MTU      Speed(Mbps) Health
Admin/Oper Status
-----
a0a      Default      a0a      up    9000      -/-      healthy
e0a      Cluster      Cluster  up    9000      auto/10000 healthy
e0b      Cluster      Cluster  up    9000      auto/10000 healthy

```