



Bridge is Unreachable over Management Network reporting for replaced bridge

https://kb-stage.netapp.com/on-prem/ontap/mc/MC-KBs/Bridge_is_Unreachable_over_Management_N...

Updated: Wed, 24 Jun 2026 07:24:49 GMT

Applies to

- Metrocluster
- ATTO Bridge

Issue

- Bridge “FB7500N107093” was replaced with the Bridge “FB7500N105891”.
- But on the Site-B, Bridge “FB7500N107093” is still reporting as present:

```
Bridge Name: ATTO_2000001086a5f680  
Bridge WWN: 2000001086a5f680
```

```
Vendor: Atto
Model: FibreBridge 7500N
Serial Number: FB7500N107093
Firmware Version: 3.40 001C
Management IP: 172.30.57.121
Errors: ATTO_2000001086a5f680(2000001086a5f680):Bridge is Unreachable over
Management Network.
Last Update Time: 8/2/2024 21:59:12 +07:00
Is Bridge Secure: false
```