



X4030S drives are failed in newly setup AFF-C800 HA pair

https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/X4030S_drives_are_failed_in_newly_setu...

Updated: Wed, 22 Apr 2026 02:10:14 GMT

Applies to

- AFF-C800
- X4030S543030TNVF drives
- ONTAP 9.12.1P5

Issue

New drives are showing as "failed" after adding two new nodes into the cluster and downgrading them into 9.12.1P5 to match the cluster ONTAP version