



E-Series EF300/EF600 controller boots into UEFI shell

https://kb-stage.netapp.com/on-prem/E-Series/Hardware-KBs/E_Series_EF300_EF600_controller_boot...

Updated: Wed, 22 Apr 2026 02:10:27 GMT

Applies to

- NetApp E-Series EF300 and EF600
- ATP M.2 mSATA device
- mSATA device firmware: Q0810B

Issue

- EF300 or EF600 controller boots into UEFI boot menu following a reset.
- The controller continues to boot into the UEFI menu even after manual reboot attempts.