



E-Series after drive replacement Drive security key identifier reports as Unknown Key ID

https://kb-stage.netapp.com/on-prem/E-Series/Hardware-KBs/E-Series_after_drive_replacement_Drive...

Updated: Wed, 24 Jun 2026 07:24:49 GMT

Applies to

- NetApp E-Series
- NetApp SANtricity

Issue

- After replacing the drive, the "Drive security key identifier" reports as "Unknown Key ID"
- The drive is Optimal state and Assigned.