



CHW-1069: Intermittent takeoverByPartnerDisabled warnings and unsynchronized logs observed on FAS9000/A700 system.

<https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CHW-1069>

Updated: Wed, 22 Apr 2026 02:10:30 GMT

Issue

- EMS report unsynchronized.

```
[monitor: monitor.globalStatus.critical:EMERGENCY]: Controller failover of
node_name_2 is not possible: unsynchronized log.
[cf_main: cf.fsm.takeoverOfPartnerDisabled:error]: Failover monitor: takeover
of NodeA disabled (unsynchronized log).
[cf_main: cf.fsm.takeoverByPartnerDisabled:error]: Failover monitor: takeover
of NodeB by NodeA disabled (unsynchronized log).
[ib_cm_wq: nvmm.mirror.aborting:debug]: mirror of sysid 1, partner_type HA
Partner and mirror state MIRROR_ONLINE is aborted because of reason Abort
Pending.
```

- Multiple instances of takeover disabled - Random NVRAM unsynchronized log reported by the nodes of the HA pair on the system.