



## ATTO FibreBridge is not secured - Active IQ Wellness Risk

[https://kb-stage.netapp.com/on-prem/ontap/mc/MC-KBs/ATTO\\_FibreBridge\\_is\\_not\\_secured\\_-\\_Active\\_I...](https://kb-stage.netapp.com/on-prem/ontap/mc/MC-KBs/ATTO_FibreBridge_is_not_secured_-_Active_I...)

Updated: Wed, 22 Apr 2026 02:10:19 GMT

### Applies to

- ONTAP 9.5 and later
- ATTO 7500N FibreBridge
- ATTO 7600N FibreBridge

### Risk Summary

The ATTO 7500N/7600N FibreBridge might reboot unexpectedly if it is not operating in secure mode. NetApp highly recommends operating ATTO 7500N/7600N FibreBridges in secure mode with ONTAP releases 9.5 and later.