



IOM12 FW version needed to support DCM2 drawers in DS460C shelves

https://kb-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/IOM12_FW_version_needed_to_support_...

Updated: Wed, 24 Jun 2026 07:24:38 GMT

Applies to

- ONTAP 9
- IOM12
- DS460C DCM2 drive drawer

Answer

IOM12 shelf module firmware version 03.00 (0300) or later is required to support DCM2 drive drawers in DS460C shelves.

If necessary, upgrade to the latest IOM12 [Disk Shelf Firmware](#).

Additional Information

NetApp has introduced an updated DS460C drive drawer, called DCM2. DCM2 drive drawers are distinguished by a blue stripe and "DCM2" label.

Related documentation: [Replace a drive drawer in a DS460C disk shelf - shelves with IOM12/IOM12B modules](#)