



Return code 0x40450037 while attempting to install NX-OS 10.3(1)F or newer on Cisco switches

https://kb-stage.netapp.com/on-prem/Switches/Cisco-KBs/Return_code_0x40450037_while_attempting...

Updated: Wed, 24 Jun 2026 07:24:39 GMT

Applies to

- 10.3(1)F or later Cisco NX-OS Software
- Cisco Cluster Interconnect Switches

Issue

Attempting to install NX-OS 10.3(1)F or later results in the following error:

```
switch# install all nxos bootflash:nxos64-cs.10.3.1.F.bin
Installer will perform compatibility check first. Please wait.
Installer is forced disruptive Verifying image
```

```
bootflash:/nxos64-cs.10.3.1.F.bin for boot variable "nxos".
[#          ] 0% -- FAIL.
Return code 0x40450037 (Not a valid nxos image). Please check the image cksum
using `show file md5sum`.
Pre-upgrade check failed. Return code 0x40450037 (Not a valid nxos image).
```